
Subject: Re: Kasino K200 Issue
Posted by [steven](#) on Wed, 04 Dec 2019 11:50:18 GMT
[View Forum Message](#) <> [Reply to Message](#)

Just because you put in new caps does not mean that they are not somewhat defective and leaky!

I test all of the new caps I get for leakage / ESR.

I would start by replacing C12 again and confirm that it's installed right.

I like to use non polarized electrolytic caps in uncoupling locations like C12.
