
Subject: Re: Kustom 100 blowing fuse
Posted by [timetraveler](#) on Sat, 13 Apr 2019 18:07:53 GMT
[View Forum Message](#) <> [Reply to Message](#)

ok i checked the caps in the 5033 board they all checkout within tolerance. the model is a hustler
