

---

Subject: Re: 250-4

Posted by [kb0rex](#) on Wed, 29 Jun 2022 16:12:55 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

I also find it interesting that these 5065 boards have an isolated ground. I don't know why they didn't use a common ground scheme and just tie it to the chassis. interesting how this was engineered back in the day.

---