

---

Subject: Re: K150-6 pumps out DC voltage when powered on.  
Posted by [steven](#) on Mon, 09 Mar 2020 09:55:26 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

How are you testing these Transistors ?

If you are using just a ohm meter test then that does not rule out that they maybe braking down when powered up.

I would try replacing CR5 with a common 1N1007 or even a 1N1004 will cut it.

---