

---

Subject: Re: K150-6 pumps out DC voltage when powered on.

Posted by [corybrown](#) on Tue, 25 Feb 2020 00:58:19 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Okay I tried swapping the big filter caps and had the same behavior. Worked find for a few minutes and then pop and hum.

I double checked the power amp board in this unit says PC 5032 Rev 1. So would it be Q5 or Q6 that you think could be the problem?

I also am using the speaker from another 8ohm cabinet that I have.

Thanks

---