

---

Subject: Re: A-4 Repair

Posted by [Jonomega3](#) on Mon, 12 Feb 2018 02:05:03 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

All good points on the NOS vs new parts, thanks!

Also great tip with the heat shrink tubing on the leads, thatll make this a lot easier. I will do the voltage test on the bias diodes tomorrow and get back with the results, thanks greatly for all the excellent info too

---