
Subject: Re: Kustom 100 blowing fuse
Posted by [steven](#) on Sun, 14 Apr 2019 10:13:11 GMT
[View Forum Message](#) <> [Reply to Message](#)

Well it seem like your back to where Bill posted, that being testing the 2 output and the driver Transistors and the string of 3 bias diodes..
Be very careful with the leads of that metal cased diode in the clip between the output Transistors as they are very fragile!
