

---

Subject: Re: 250-4

Posted by [steven](#) on Mon, 04 Jul 2022 21:02:48 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

I think one of your problems all along was a leaky 2N3055/36892/NTE130.

---