

---

Subject: Re: K150-6 pumps out DC voltage when powered on.  
Posted by [chicagobill](#) on Sun, 15 Mar 2020 01:58:59 GMT  
[View Forum Message](#) <> [Reply to Message](#)

---

Yes, there is a way to reuse the heatsinks, but it is not a simple job.

For testing, you don't need to have the heatsinks on the replacement transistors. The amp will need the heatsinks if you drive the amp hard and for an extended period of time.

Did you try testing Q4 or removing C7?

---