

---

Subject: Re: 250-4

Posted by [steven](#) on Fri, 24 Jun 2022 15:23:33 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

A easy test to make if you can't test the 4 outputs directly for leakage is to swap them in pairs around each side of the thermal breaker.

If the + .210 VDC you have on the jack goes to a negative, then one of those two outputs on the negative rail is leaking, or one of them is very very unmatched to the other 3 .

All K 250 and 150 metal face amps like you have, have or had a reverb lock.

I guess you now have a hole in the center rear of the back panel?

---