

---

Subject: Re: A-4 Repair

Posted by [Jonomega3](#) on Thu, 08 Feb 2018 20:12:07 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Sorry, just getting back to the A-4 after getting side tracked a bit. I am ready to move forward replacing the modifications with the appropriate parts, any suggestions? Thanks! FYI, I did put a 10uf 16v cap in place of the 22uf 25v that was in C702

---