

---

Subject: Re: Repair

Posted by [NLKustom](#) on Fri, 30 Sep 2022 20:00:41 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

I've looked inside the tank. the sponge was been peeled back before I bought it. The springs are attached and everything looks fine inside.

Obviously something is weak somewhere in the reverb system.

---