

---

Subject: Re: K150-6 pumps out DC voltage when powered on.

Posted by [corybrown](#) on Fri, 06 Mar 2020 23:59:42 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Well the new Q4 came in today. Replaced it and sadly it did not fix the problem. I now have -20V instead of -27V so I guess we are going in the right direction.

The only other component that had funny measurements was Q12 but I didn't order any of those. I did unsolder it and remove it from the board and tested it with DMM and it tests good.

So where to next?

---