

---

Subject: Re: K150-6 pumps out DC voltage when powered on.  
Posted by [corybrown](#) on Sat, 21 Mar 2020 15:57:22 GMT  
[View Forum Message](#) <> [Reply to Message](#)

---

Okay well the new part for C7 came in. I got 47p 100V 10% from newark.

I also reinstalled all of the old components and installed this new capacitor to replace c7. We are indeed stable and it is no longer going into fail mode.

However I just noticed in my meddling that I broke the leads off of CR3. I was warned against this and now I've done it.

What is the replacement part for that?

---