

---

Subject: Re: Schematic Accuracy

Posted by [chicagobill](#) on Thu, 13 Feb 2014 19:40:59 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Okay, I didn't understand and I also didn't look at the schematic. The 2N4249 is the generic number, the 38734 is the Kustom part number for the equivalent transistor.

What is it about the main 40 volt supply that you are trying to fix?

Q131 is shown on the transistor layout between Q115 and Q107 just above the speed control R148.

---