
Subject: Re: K150-6 pumps out DC voltage when powered on.
Posted by [chicagobill](#) on Sun, 08 Mar 2020 23:43:46 GMT
[View Forum Message](#) <> [Reply to Message](#)

I thought that you replaced Q4 with an NTE128.

I'd try using the NTE129 to replace Q6 and see what happens.
