
Subject: Kustom III lead pc board 5065 rev2

Posted by [podbaydoors](#) on Wed, 05 Jun 2019 14:19:09 GMT

[View Forum Message](#) <> [Reply to Message](#)

Hi all,

Just signed up for the forum.

I realize that this forum is primarily Tuck 'n Roll (I used to have a Tuck 'n Roll head, last I heard it was in Vancouver) but my question today for those wiser than me regards a Kustom III Lead.

It is all original, and still working after a fashion.

All the electrolytic caps will be replaced which should help to preserve it's operating status for a good many more years.

The question I have regards one resistor on the PC 5065 rev 2 board.

The second from the right 1/4 watt brown bodied resistor that obviously was overheated.

Does anyone have the schematic / layout info on this board in this revision?

Can anyone tell me what the value of this resistor is supposed to be?

Best regards,

Lou
