

---

Subject: Re: Kustom 100 blowing fuse

Posted by [chicagobill](#) on Tue, 23 Apr 2019 16:30:28 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

The 1% resistors that you are talking about are part of the protection circuit. In a working amp, they read the voltage on the ballast resistors and when the voltage gets too high, they reduce the signal to the driver transistor to lower the output signal. Off values will cause the protection circuit to either trigger too early or too late.

The amp would work without the entire protection circuit if it was removed.

---