
Subject: 2-15 B Ports Blocked

Posted by [Bobby Stevens](#) on Sun, 02 Jun 2024 22:50:42 GMT

[View Forum Message](#) <> [Reply to Message](#)

Just bought my first Kustom rig, K250-1 with 2-15 B cab loaded with JBL D140's. I think the amp and cab sound pretty great as is. But when I removed the back to check the speaker brand, I noticed the ports are blocked. It looks like work that was done a long time ago, and I am wondering if perhaps it was done in the factory. I have pictures to upload, but the icon in the post form doesn't seem to be working for me. Did they block ports depending on what speakers were used?

Thanks in advance for the insight,
Bobby

Subject: Re: 2-15 B Ports Blocked

Posted by [steven](#) on Mon, 03 Jun 2024 10:14:03 GMT

[View Forum Message](#) <> [Reply to Message](#)

Is the 250 head one tuck & roll pleat wider then the speaker cab?

Note that pictures can not be posted to this site.

Subject: Re: 2-15 B Ports Blocked

Posted by [Bobby Stevens](#) on Fri, 07 Jun 2024 03:04:48 GMT

[View Forum Message](#) <> [Reply to Message](#)

It overhangs the cabinet by maybe 1/4" on each side.

Subject: Re: 2-15 B Ports Blocked

Posted by [steven](#) on Fri, 07 Jun 2024 10:01:24 GMT

[View Forum Message](#) <> [Reply to Message](#)

Early heads and vertical cabinets where 11 pleats wide, later ones are 12 wide.
