

---

Subject: Re: A-4 Repair

Posted by [steven](#) on Tue, 30 Jan 2018 20:24:14 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Two resistors in that string of 4 are 33k and two are 6.8k , if someone was going for 82k which is used on a 702 board then they are way short!

Go over the schematic carefully and take out what should not be there as a start.

---