

---

Subject: Re: 250-4

Posted by [kb0rex](#) on Wed, 13 Jul 2022 19:13:53 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

If I jumper from input to r6 on amp board, I have good loud signal I may now still have preamp problems. With jumper in place its loud and not getting hot anymore, so some progress

---