Subject: Re: Repair Posted by stevem on Sat, 01 Oct 2022 00:05:37 GMT View Forum Message <> Reply to Message

Poor connections (metal to metal) with the jacks and plugs can make for a high impedance with can make the pan go nuts and feedback.

With one end of each rca cable unplugged spin the other end while it's plugged in a good number of times.

This will hopefully untarnish the connection points where there very had to Get at.

Page 1 of 1 ---- Generated from VintageKustom.com