

---

Subject: Re: K200A-1 Power Amp Rescue Needed  
Posted by [thetragichero](#) on Sun, 28 Apr 2019 04:14:57 GMT  
[View Forum Message](#) <> [Reply to Message](#)

---

done for the night, but as I was testing resistors for my switch to cascade channel 1 into channel 2 (because channel 1 out is too hot a signal to just run right into channel 2 in) I watched r716 (probably the only 100r resistor I didn't replace on that board) let out some magic smoke and my amp go really quiet  
guess it's time to dig around for a new resistor

---