
Subject: Re: K150-6 pumps out DC voltage when powered on.
Posted by [chicagobill](#) on Sun, 30 Aug 2015 18:12:54 GMT
[View Forum Message](#) <> [Reply to Message](#)

Have you tightened the screws on top of the two main filter caps? How about the wires going to the power transistors?

You can also try pushing on different components, using a wooden stick while amp is on to see if you can find something loose.
