

---

Subject: Dead K 100 Piggyback

Posted by [Breakersbass](#) on Fri, 07 Oct 2016 21:04:38 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

I was given a beautiful Blue K100 piggyback last week. When I got it home I found at some point roaches had decided to hang out. The amp is dead. Once I cleaned all the bugs I started to look into the issue. I have about 38 volts on both pilot lamp leads and I found where someone had replaced a SE 4002 (located at the bottom of the board on the right side) with a 2s transistor. I replaced it with the suitable sub for the SE 4002. Any thoughts on where I should look. Any help will be appreciated.

---