

---

Subject: Re: Kustom 100 blowing fuse  
Posted by [timetraveler](#) on Fri, 07 Jun 2019 16:17:25 GMT  
[View Forum Message](#) <> [Reply to Message](#)

---

looks like the one output transistor is grounding to the chassis. any recommendations? do they sell just the plastic washer things or do i need to buy another transistor.

---