

---

Subject: Re: A-4 Repair

Posted by [Jonomega3](#) on Mon, 12 Feb 2018 15:10:53 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

At CR701 I have .9v at the end of CR703 I have -387mv My math is terrible but I think that is close to 1.5 volt difference? Maybe 1.3 rounded off

---