

---

Subject: Re: A-4 Repair

Posted by [steven](#) on Mon, 20 Aug 2018 16:27:04 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

A replacement for that is a NTE128 , this is a TO39 case transistor like the original but without the heat sink so you will need to also get a slip on star type heat sink to make it live.

---