
Subject: Re: Schematic Accuracy
Posted by [bluezebra](#) on Wed, 12 Feb 2014 17:55:12 GMT
[View Forum Message](#) <> [Reply to Message](#)

Hello Stevem

Every transistor on this board was changed out to new and triple checked for orientation.
