
Subject: Re: K150-6 pumps out DC voltage when powered on.
Posted by [corybrown](#) on Mon, 09 Mar 2020 15:59:50 GMT
[View Forum Message](#) <> [Reply to Message](#)

Just ordered some more parts.

I have NTE128 to replace Q5.
NTE129 to replace Q6
1N1007 to replace CR5.

I'll let you know how it goes.

Thanks
