

---

Subject: Re: Repair

Posted by [NLKustom](#) on Mon, 26 Sep 2022 00:46:00 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Sorry for the long delay in a reply. Been busy with work.

Finally got a look inside the amp tonight. The springs in the tank are fine. Replaced the RCA chord to the input side with a new one and the buzzing went away.

---