
Subject: Re: 250-4

Posted by [kb0rex](#) on Thu, 14 Jul 2022 15:56:27 GMT

[View Forum Message](#) <> [Reply to Message](#)

so it looks like I take out the 3-wire jumper from 5066 to 5069 and jumper 5069 j1 pin1 to pin 2..
ok will report back
