

---

Subject: Re: Kustom 100 blowing fuse

Posted by [timetraveler](#) on Mon, 22 Apr 2019 21:02:44 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

thanks for all the help. Right now im trying to replace a resistor but going from the 5033 hustler diagram the lower diagram says its r24 but the top diagram says r24 is a 5w .51 resistor and i know thats not right the resistor is burned so i cant read the stripes

---