

---

Subject: Re: Repair advise

Posted by [chicagobill](#) on Mon, 12 Aug 2013 16:57:42 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Yes, the PC102 circuits are the same for both amps.

Do you have the footswitch for your amp? If you do, turn on and off each of the FX and see if the signal on the dead channel comes through. If you don't have the footswitch, then use a jumper wire to short each of the 4 pins to the chassis.

On the K200A series amps, all of the FX are normally turned off until you turn them on with the footswitch.

---