
Subject: Re: Kustom 100 blowing fuse
Posted by [timetraveler](#) on Mon, 10 Jun 2019 19:16:50 GMT
[View Forum Message](#) <> [Reply to Message](#)

ok i tested both output transistors and they both look good on all tests
