

---

Subject: Re: Repair

Posted by [steven](#) on Fri, 22 Jul 2022 20:25:29 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Have you peeled back the cover on the reverb tank to look in it ?

Your saying that your reverb is weak a long with this issue now makes me think that you have one busted spring of the two in the tank.

If so I can tell you how to fix it.

Your tremolo volume drop issue I will look into on Sunday or Monday when I get back from a short getaway

---