Subject: 2-15 B Ports Blocked Posted by Bobby Stevens on Sun, 02 Jun 2024 22:50:42 GMT View Forum Message <> Reply to Message

Just bought my first Kustom rig, K250-1 with 2-15 B cab loaded with JBL D140's. I think the amp and cab sound pretty great as is. But when I removed the back to check the speaker brand, I noticed the ports are blocked. It looks like work that was done a long time ago, and I am wondering if perhaps it was done in the factory. I have pictures to upload, but the icon in the post form doesn't seem to be working for me. Did they block ports depending on what speakers were used?

Thanks in advance for the insight, Bobby

Page 1 of 1 ---- Generated from VintageKustom.com