Subject: Re: A-4 Repair

Posted by Jonomega3 on Sun, 28 Jan 2018 20:44:46 GMT

View Forum Message <> Reply to Message

Yes, sorry I did mean circuit breakers. Looks like the on/off switch has been replaced

Pc 702 for power amp.

Im going to try and get some pics posted later, there looks to be some boogering in the power amp section that might help if you see. There are 4 resistors coupled together with a 250v 4.7 electrolytic cap going to ground that doesn't look like it belongs fyi