

---

Subject: Re: 250-4

Posted by [steven](#) on Thu, 30 Jun 2022 10:12:19 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

At times when I have worked on these boards in amp I have ran a ground wire from the molex connector trace back to the common of the rail filters so I don't have to have the molex plugged in.

When I have done this I have never noticed a increase or decrease in 120 hum / noise level in the amps output so I remove the wire when I am done.

---