
Subject: Re: A-4 Repair

Posted by [Jonomega3](#) on Sat, 25 Aug 2018 11:58:21 GMT

[View Forum Message](#) <> [Reply to Message](#)

Yes distortion in both channels,
so 13 volts should at 40410 base, not 15v? I'm not getting any voltage there. I'm getting a little more than 1 volt at the input of the 1st diode
