Subject: Re: 250-4

Posted by stevem on Fri, 24 Jun 2022 10:20:32 GMT

View Forum Message <> Reply to Message

There held on with four 6/32" machine screws if I recall right, and you mean to tell me they rotted away, or did the metal reverb lock disc come off its handle and fall down?

With this lock on rear set I don't think that tank can fall that far!

I will open one of mine on the weekend and confirm the size of the machine screws for you.

Note that most times you can find the correct 1N3754 bias diode being sold on eBay, or 4 star electronics and other N.O.S suppliers have them.

I would get the correct one even if it's 15 bucks!

PS.

I too have been logged off the site somehow when typing a long reply and then going to post it , so don't feel bad, lol!