

---

Subject: Re: A-4 Repair

Posted by [Jonomega3](#) on Tue, 30 Jan 2018 18:24:39 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Really glad you can finally see the pics even though theyre hard on the eyes! haha. This is the model with circuit breakers no fuses. And they appear to be original with the date of 67' and also appear connected correctly.

OK I'll take those resistors and 4.7 cap out, did you notice that added 22uf 25 volt cap coupled with the .47 cap that is in proximity of that mess? According to schematics its foreign as well.

Could those coupled 4 resistors and 4.7 cap be originally an 82k resistor? Im thinking If Im reading the schematics correctly it could be

---