

---

Subject: Re: A-4 Repair

Posted by [Jonomega3](#) on Thu, 16 Aug 2018 22:51:15 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

So, the driver transistors are the 4 inside the heat shields? If so, I have the numbers 38736 and 38737 2 of each, all RCA in there now. I suppose these numbers are not the type of transistor I need to order?

---